

APPENDIX C

GREENPATH IR CAMERA INSPECTION REPORT

Third-Party Verification Final Audit Report Second Audit

Noble Energy, Inc.
1625 Broadway, Suite 2200
Denver, CO 80202

September 25, 2020

Date	29-Aug-18
Prepared By	Joshua Anhalt Cell# 403-200-1553 email: janhalt@greenpathenergy.com
Report Type	2018 CD Audit Sites for IR Camera Inspection



GreenPath Survey Date	GreenPath Rep	On-Site Noble Rep	LOD	Process	Emission Detected	Emission Description	Component Type	GPE Media #	GPE Reinspection Media #	Noble Notification Phone Call ?	Noble Rep Notified	Repaired During Survey ?	Repair By	Verified By	Repair Notes
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR CUTLER METZ SELLS UPRC T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	11954	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR CUTLER METZ SELLS UPRC T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	11955	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR CUTLER METZ SELLS UPRC T4N-R65W-S31 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11956	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR CUTLER METZ SELLS UPRC T4N-R65W-S31 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11957	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR KIRKHAM TUDOR T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	11958	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR KIRKHAM TUDOR T4N-R65W-S31 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11959	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HSR KIRKHAM TUDOR T4N-R65W-S31 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11961	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HARTMAN KOSKELA LAURICE SHELTON T3N-R65W-S1 L01	Oil Tank	No	No leak(s) detected	n/a	11963	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HARTMAN KOSKELA LAURICE SHELTON T3N-R65W-S1 L01	Oil Tank	No	No leak(s) detected	n/a	11964	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HARTMAN KOSKELA LAURICE SHELTON T3N-R65W-S1 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11965	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	HARTMAN KOSKELA LAURICE SHELTON T3N-R65W-S1 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11966	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SCOOTER HORNTON T3N-R64W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	11967	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SCOOTER HORNTON T3N-R64W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	11968	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SCOOTER HORNTON T3N-R64W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	11969	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SCOOTER HORNTON T3N-R64W-S18 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11970	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SCOOTER HORNTON T3N-R64W-S18 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11971	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SARCHET T3N-R65W-S24 L02	Oil Tank	No	No leak(s) detected	n/a	11972	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SARCHET T3N-R65W-S24 L02	Oil Tank	No	No leak(s) detected	n/a	11973	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SARCHET T3N-R65W-S24 L02	Oil Tank	No	No leak(s) detected	n/a	11974	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SARCHET T3N-R65W-S24 L02	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11975	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SARCHET T3N-R65W-S24 L02	Tank VOC Burner #1	No	No leak(s) detected	n/a	11976	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CORBIN RED T3N-R64W-S30 L01	Oil Tank	No	No leak(s) detected	n/a	11977	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CORBIN RED T3N-R64W-S30 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11978	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CORBIN RED T3N-R64W-S30 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11979	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CANNON T3N-R65W-S35 L03	Oil Tank	No	No leak(s) detected	n/a	11980	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CANNON T3N-R65W-S35 L03	Oil Tank	No	No leak(s) detected	n/a	11981	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CANNON T3N-R65W-S35 L03	Oil Tank	No	No leak(s) detected	n/a	11982	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CANNON T3N-R65W-S35 L03	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11983	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	CANNON T3N-R65W-S35 L03	Tank VOC Burner #1	No	No leak(s) detected	n/a	11984	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	NORRIS PIONEER T2N-R64W-S8 L01	Oil Tank	No	No leak(s) detected	n/a	11985	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	NORRIS PIONEER T2N-R64W-S8 L01	Oil Tank	No	No leak(s) detected	n/a	11986	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	NORRIS PIONEER T2N-R64W-S8 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11987	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	NORRIS PIONEER T2N-R64W-S8 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11988	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SEMMEUS USX UPRR SLOAN T2N-R64W-S17 L01	Oil Tank	No	No leak(s) detected	n/a	11989	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SEMMEUS USX UPRR SLOAN T2N-R64W-S17 L01	Oil Tank	No	No leak(s) detected	n/a	11990	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SEMMEUS USX UPRR SLOAN T2N-R64W-S17 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11991	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	SEMMEUS USX UPRR SLOAN T2N-R64W-S17 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	11992	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Oil Tank	No	No leak(s) detected	n/a	11993	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Oil Tank	No	No leak(s) detected	n/a	11994	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Oil Tank	No	No leak(s) detected	n/a	11995	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Oil Tank	No	No leak(s) detected	n/a	11996	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	11998	n/a	n/a	n/a	n/a	n/a	n/a	n/a
23-Aug-18	Joshua Anhalt	Matt Rusch	RICHEY T3N-R65W-S27 L03	Tank VOC Burner #1	No	No leak(s) detected	n/a	11997	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	BERIG ST T4N-R66W-S36 L02	Oil Tank	No	No leak(s) detected	n/a	11999	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	BERIG ST T4N-R66W-S36 L02	Oil Tank	No	No leak(s) detected	n/a	12000	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	BERIG ST T4N-R66W-S36 L02	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12001	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	BERIG ST T4N-R66W-S36 L02	Tank VOC Burner #1	No	No leak(s) detected	n/a	12002	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12003	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12004	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12005	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12006	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12007	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Oil Tank	No	No leak(s) detected	n/a	12008	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12009	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	FIVE RIVERS T4N-R66W-S4 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12010	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	HANSEN T4N-R67W-S1 L01	Oil Tank	No	No leak(s) detected	n/a	12011	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	HANSEN T4N-R67W-S1 L01	Oil Tank	No	No leak(s) detected	n/a	12012	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	HANSEN T4N-R67W-S1 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12013	n/a	n/a	n/a	n/a	n/a	n/a	n/a
20-Aug-18	Joshua Anhalt	Matt Rusch	STORIS E24 & MACKINAW A19 ECONODE T6N-R65W-S24 L01	Oil Tank	Yes	Thief hatch seal	Tank thief hatch center assembly	11654	11669	Yes	Yes	Yes	Josh Hays	GreenPath- Joshua	Center Assemble replace w/ new - Verified ok
24-Aug-18	Joshua Anhalt	Matt Rusch	SUSAN WESTERN T5N-R67W-S35 L01	Oil Tank	No	No leak(s) detected	n/a	12017	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	SUSAN WESTERN T5N-R67W-S35 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12018	n/a	n/a	n/a	n/a	n/a	n/a	n/a
24-Aug-18	Joshua Anhalt	Matt Rusch	SUSAN WESTERN T5N-R67W-S35 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12019	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MASSEY SIAMA RURAL T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	12020	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MASSEY SIAMA RURAL T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	12021	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MASSEY SIAMA RURAL T4N-R65W-S31 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12022	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MASSEY SIAMA RURAL T4N-R65W-S31 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12023	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	RURAL T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	12024	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	RURAL T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	12025	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	RURAL T4N-R65W-S31 L01	Oil Tank	No	No leak(s) detected	n/a	12026	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	RURAL T4N-R65W-S31 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12027	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	RURAL T4N-R65W-S31 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12028	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MARSHALL MEL SMOOKLER RURAL LAND T4N-R65W-S32 L01	Oil Tank	No	No leak(s) detected	n/a	12029	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MARSHALL MEL SMOOKLER RURAL LAND T4N-R65W-S32 L01	Oil Tank	No	No leak(s) detected	n/a	12030	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MARSHALL MEL SMOOKLER RURAL LAND T4N-R65W-S32 L01	Oil Tank	No	No leak(s) detected	n/a	12031	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MARSHALL MEL SMOOKLER RURAL LAND T4N-R65W-S32 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12032	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	MARSHALL MEL SMOOKLER RURAL LAND T4N-R65W-S32 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12033	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	HANSCOME T4N-R64W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12034	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	HANSCOME T4N-R64W-S21 L02	Oil Tank	No	No leak(s) detected	n/a	12035	n/a	n/a	n/a	n/a	n/a	n/a	n/a
27-Aug-18	Joshua Anhalt	Matt Rusch	HANSCOME T4N-R64W-S21 L03	Oil Tank	No	No leak(s) detected	n/a	12036	n/a	n/a	n/a	n/a	n/a	n/a	n/a

Date	29-Aug-18
Prepared By	Joshua Anhalt Cell# 403-200-1553 email: janhalt@greenpathenergy.com
Report Type	2018 CD Audit Sites for IR Camera Inspection



GreenPath Survey Date	GreenPath Rep	On-Site Noble Rep	LOD	Process	Emission Detected	Emission Description	Component Type	GPE Media #	GPE Reinspection Media #	Noble Notification Phone Call ?	Noble Rep Notified	Repaired During Survey ?	Repair By	Verified By	Repair Notes
28-Aug-18	Joshua Anhalt	Matt Rusch	ALOYSIUS 2E RANCHES T4N-R64W-S34 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12122	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	ALOYSIUS 2E RANCHES T4N-R64W-S34 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12123	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR SHABLE HINDE VANDLEN PECK KRISAL T4N-R65W-S20 L01	Oil Tank	No	No leak(s) detected	n/a	12124	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR SHABLE HINDE VANDLEN PECK KRISAL T4N-R65W-S20 L01	Oil Tank	No	No leak(s) detected	n/a	12125	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR SHABLE HINDE VANDLEN PECK KRISAL T4N-R65W-S20 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12126	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR SHABLE HINDE VANDLEN PECK KRISAL T4N-R65W-S20 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12127	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	SPAYD T4N-R65W-S29 L01	Oil Tank	No	No leak(s) detected	n/a	12128	n/a	n/a	n/a	n/a	n/a	n/a	n/a
21-Aug-18	Joshua Anhalt	Matt Rusch	UPRC CHEWY T5N-R64W-S23 L01	Tank VOC Burner #1	Yes	Combustor Oz Guage Face	Replace w/ new guage	11764	11765	Yes	Yes	Yes	Josh Hays	GreenPath- Joshua	Prssure Guage replace w/ new - Verified ok
28-Aug-18	Joshua Anhalt	Matt Rusch	SPAYD T4N-R65W-S29 L01	Oil Tank	No	No leak(s) detected	n/a	12130	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	SPAYD T4N-R65W-S29 L01	Oil Tank	No	No leak(s) detected	n/a	12131	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	SPAYD T4N-R65W-S29 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12132	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	SPAYD T4N-R65W-S29 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12133	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	KATE WHITE JESSIE T3N-R64W-S29 L01	Oil Tank	No	No leak(s) detected	n/a	12134	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	KATE WHITE JESSIE T3N-R64W-S29 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12135	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	KATE WHITE JESSIE T3N-R64W-S29 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12136	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR KRAUSE T4N-R65W-S28 L01	Oil Tank	No	No leak(s) detected	n/a	12137	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR KRAUSE T4N-R65W-S28 L01	Oil Tank	No	No leak(s) detected	n/a	12138	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR KRAUSE T4N-R65W-S28 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12139	n/a	n/a	n/a	n/a	n/a	n/a	n/a
28-Aug-18	Joshua Anhalt	Matt Rusch	HSR KRAUSE T4N-R65W-S28 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12140	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	CARPIO GRUEN OTTINGER T6N-R64W-S22 L01	Oil Tank	No	No leak(s) detected	n/a	12141	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	CARPIO GRUEN OTTINGER T6N-R64W-S22 L01	Oil Tank	No	No leak(s) detected	n/a	12142	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	CARPIO GRUEN OTTINGER T6N-R64W-S22 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12143	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	CARPIO GRUEN OTTINGER T6N-R64W-S22 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12144	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	12145	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	12146	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	12147	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	12148	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Oil Tank	No	No leak(s) detected	n/a	12149	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Produced Water	No	No leak(s) detected	n/a	12150	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12151	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	SLW GREEN VINCE ST T5N-R63W-S18 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12152	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12153	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12154	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12155	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12156	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12157	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12158	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12159	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12160	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Oil Tank	No	No leak(s) detected	n/a	12161	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12162	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12163	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	70 RANCH T5N-R63W-S21 L01	Tank VOC Burner #2	No	No leak(s) detected	n/a	12164	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	REI FED BEEBE DRAW OVIATT T3N-R65W-S10 L01	Oil Tank	No	No leak(s) detected	n/a	12165	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	REI FED BEEBE DRAW OVIATT T3N-R65W-S10 L01	Oil Tank	No	No leak(s) detected	n/a	12166	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	REI FED BEEBE DRAW OVIATT T3N-R65W-S10 L01	Oil Tank	No	No leak(s) detected	n/a	12167	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	REI FED BEEBE DRAW OVIATT T3N-R65W-S10 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12168	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	REI FED BEEBE DRAW OVIATT T3N-R65W-S10 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12169	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12171	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12172	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12173	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12174	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12175	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12176	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12177	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Oil Tank	No	No leak(s) detected	n/a	12178	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12179	n/a	n/a	n/a	n/a	n/a	n/a	n/a
29-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Tank VOC Burner #1	No	No leak(s) detected	n/a	12180	n/a	n/a	n/a	n/a	n/a	n/a	n/a
30-Aug-18	Joshua Anhalt	Matt Rusch	THOMPSON T4N-R64W-S28 L03	Tank VOC Burner #2	No	No leak(s) detected	n/a	12181	n/a	n/a	n/a	n/a	n/a	n/a	n/a
30-Aug-18	Joshua Anhalt	Matt Rusch	SATER T4N-R63W-S19 L01	Oil Tank	No	No leak(s) detected	n/a	12182	n/a	n/a	n/a	n/a	n/a	n/a	n/a
30-Aug-18	Joshua Anhalt	Matt Rusch	SATER T4N-R63W-S19 L01	Oil Tank	No	No leak(s) detected	n/a	12183	n/a	n/a	n/a	n/a	n/a	n/a	n/a
30-Aug-18	Joshua Anhalt	Matt Rusch	SATER T4N-R63W-S19 L01	Tank VOC Manifold Knock Out & Piping	No	No leak(s) detected	n/a	12184	n/a	n/a	n/a	n/a	n/a	n/a	n/a
30-Aug-18	Joshua Anhalt	Matt Rusch	SATER T4N-R63W-S19 L01	Tank VOC Burner #1	No	No leak(s) detected	n/a	12185	n/a	n/a	n/a	n/a	n/a	n/a	n/a